

F4 Technical Advisory Memo

No: TAMF4-2020-0287

Date: July 28, 2020

Subject: HPD Bulletin F4-2020-EN004-00 Cam Cover Breather Safety

See the attached HPD bulletin requiring safety wire installation on the cam cover breather. This process must be done exactly as described and as shown in the photograph in the bulletin.

This is a mandatory upgrade.

The breather safety wire must be installed prior to participation in the 2020 event at Barber.