




SCCA Spec Miata NA/NB Package Shelf Trim Guidelines

Per GCR Section 9.1.7.3.C.8.1, this document outlines the only approved trimming of the package shelf once the OEM seat belt towers are removed. Any trimming or modification not outlined in this document could be deemed illegal and subject to penalties outlined in the GCR.







Seat belt tower trim must be done along the vertical seam.



Hard top mounting holes may not be removed.

Horizontal trim may not effect the inner panel that you are required to keep.

Areas in Pink may be removed.

Areas in Green may NOT be removed or modified.

(Drivers side of vehicle)




Seat belt tower trim must be done along the vertical seam.




Hard top mounting holes may not be removed.

Horizontal trim may not effect the inner panel that you are required to keep.

Areas in Pink may be removed.

Areas in Green may NOT be removed or modified.







SCCA - NA/NB Package Shelf Trim Guidelines

