

FRA Engine Harness Maintenance Technical Bulletin # FRA-2020-EL001-00

Approval



This Technical Bulletin provides information concerning the inspections and maintenance of the FRA harness.

Procedure:

Upon the completion of a season's worth of on track activity it is recommended by HPD that all FRA engine harnesses are sent in for inspection and potential maintenance. Inspections and maintenance will be performed by BMRS Wired Racing Electrical Solutions. Please ship your engine harness directly to BMRS. Along with the engine harness please include the provided New Customer Information Form regardless of your status with BMRS so that billing and return information is associated to your harness. Payment for service will be direct to BMRS. All inspection costs are quoted at \$50, additional costs may be needed if servicing of the harness is necessary.

Note: Please clean the engine harness prior sending out for inspection.

Shipping details are as follows:

BMRS Wired Racing Electrical Solutions

Address: 1 Carpenter Court NW, Suite #300 Concord, North Carolina 28027

Please note attention for SuzAnn Hamilton.

If you have any questions regarding the content of this bulletin, please contact John Whiteman at jwhiteman@hra.com or GRMS Admin at GRMSAdmin@hra.com.

This document is confidential and is supplied on express condition that it shall not be lent, copied, or disclosed to any other person, or used for any other purpose without the written consent of Honda Performance Development.