

F3 Technical Advisory Memo

No: TAMF3-2019-014
Date: December 16, 2019
Subject: HPD Bulletin F3-2020-EN001 Engine Vendor Change

See this HPD bulletin for information on the change in engine service provider.

TRBF3-2019-004 (released this date) and TAMF3-2019-015 (to be released soon) have specifics on written notification to SCCA and HPD prior to engine service, repair, or power confirmation.

To be clear, while the HPD bulletin requires prior notice to HPD, prior notice will also be required to SCCA Pro Racing, as explained in TRBF3-2019-004.