

## FR Technical Advisory Memo

**No:** TAMFR-2020-015

**Date:** June 12, 2020

**Subject:** HPD Bulletin FRA-2020-EN003-00 Oil Pump Recall

HPD has found that oil pumps from a specific batch have a defect that could result in loss of oil pump failure.

See the attached HPD bulletin for details.