

Stewards Decisions - Teams
2020 F4 United States and FR Americas Championships



Competitor	Car #	Class	Circuit	Session Date	Session	Article # / Offense:	Decision	Rep	Fine	Dec. #
Abel Motorsports	15	FR	Barber Motorsports Park	01 August 2020	Race 1	26.3(b) - Fire extinguisher not in armed position for on track session	Team reprimand	1	\$ -	311
Abel Motorsports							Total Reprimands and Fines	1	\$ -	
Alliance Racing	33	F4	Barber Motorsports Park	31 July 2020	Practice 1	24.5 - Non-compliant practice tires	Start at back of qualifying grid and three grid places at next race	-	\$ -	307
Alliance Racing	03	F4	Virginia International Raceway	17 July 2020	Practice 1	23.6 - Failed to complete pre-event scrutineering	Team reprimand	1	\$ -	203
Alliance Racing							Total Reprimands and Fines	1	\$ -	
Crosslink/Kiwi Motorsport	32	F4	Barber Motorsports Park	01 August 2020	Race 2	26.1/Technical Regulations 2.7.1 - Floor obtained from a source other than manufacturer	Start race from pit lane and team fine	-	\$ 1,500	313
Crosslink/Kiwi Motorsport	14	F4	Virginia International Raceway	18 July 2020	Qualifying	26.1/Technical Regulations 2.7.1 - Front brake rotor not as delivered/Type 1 part replaced from source other than manufacturer	Team reprimand and fine	1	\$ 250	207
Crosslink/Kiwi Motorsport	14	F4	Mid-Ohio Sports Car Course	28 June 2020	Race 2	Protest - 26.1 - Alleged non-compliant flywheel	Protest disallowed	-	\$ -	127
Crosslink/Kiwi Motorsport	14	F4	Mid-Ohio Sports Car Course	28 June 2020	Race 2	Protest - 26.1 - Alleged non-compliant fuel cell	Protest disallowed	-	\$ -	126
Crosslink/Kiwi Motorsport	14	F4	Mid-Ohio Sports Car Course	28 June 2020	Race 2	Protest - 26.1 - Alleged non-compliant gear box (not as supplied)	Protest disallowed	-	\$ -	125
Crosslink/Kiwi Motorsport	91	F4	Mid-Ohio Sports Car Course	28 June 2020	Race 2	26.9 - Video cards submitted late or without recorded video, or not submitted	Team fine	-	\$ 100	121
Crosslink/Kiwi Motorsport							Total Reprimands and Fines	1	\$ 350	
DC Autosport	51	F4	Virginia International Raceway	18 July 2020	Race 1	26.3(b) - Fire extinguisher not in armed position for on track session	Team reprimand	1	\$ -	213
DC Autosport							Total Reprimands and Fines	1	\$ -	
DEForce Racing	22	F4	Virginia International Raceway	17 July 2020	Practice 2	26.9 - Video cards submitted late or without recorded video, or not submitted	Team reprimand	1	\$ -	205
DEForce Racing							Total Reprimands and Fines	1	\$ -	
HMD Motorsports	55	FR	Mid-Ohio Sports Car Course	26 June 2020	Qualifying	26.9 - Video cards submitted late or without recorded video, or not submitted	Team fine	-	\$ 100	107
HMD Motorsports							Total Reprimands and Fines	-	\$ 100	
Iron Rock Motorsports	26	F4	Mid-Ohio Sports Car Course	27 June 2020	Race 1	39.5(b) - Car worked on during a race suspension	Team reprimand	1	\$ -	116
Iron Rock Motorsports							Total Reprimands and Fines	1	\$ -	
Jay Howard Driver Development	4	F4	Barber Motorsports Park	01 August 2020	Race 2	26.1/Technical Regulations 2.7.1 - Modified floor	Disqualification and team fine	-	\$ 3,000	312
Jay Howard Driver Development	6	F4	Barber Motorsports Park	01 August 2020	Race 1	26.1/Technical Regulations 2.7.1 - Oil pickup tube installed reversed	Five grid places and team fine	-	\$ 750	310
Jay Howard Driver Development	5	F4	Barber Motorsports Park	01 August 2020	Race 1	26.1/Technical Regulations 2.7.1 - Oil pickup tube installed reversed	Five grid places and team fine	-	\$ 750	309
Jay Howard Driver Development	3	F4	Virginia International Raceway	19 July 2020	Race 3	26.9 - Video cards submitted late or without recorded video, or not submitted	Team fine	-	\$ 100	229

Stewards Decisions - Teams
2020 F4 United States and FR Americas Championships



Competitor	Car #	Class	Circuit	Session Date	Session	Article # / Offense:	Decision	Rep	Fine	Dec. #
Jay Howard Driver Development	3,4,5,6,8	F4	Virginia International Raceway	19 July 2020	Race 2	24.3 - Non-compliant qualifying or race tires	Team reprimand	1	\$ -	222
Jay Howard Driver Development	5	F4	Virginia International Raceway	19 July 2020	Race 2	28.2 - Change of engine for any reason	Five grid places and team fine	-	\$ 2,500	218
Jay Howard Driver Development	8	F4	Mid-Ohio Sports Car Course	28 June 2020	Race 2	26.1/Technical Regulations 2.7.1 - Modified engine oil pressure sensor	Disqualification and team fine	-	\$ 3,000	133
Jay Howard Driver Development	7	F4	Mid-Ohio Sports Car Course	28 June 2020	Race 2	26.1/Technical Regulations 2.7.1 - Modified engine oil pressure sensor	Disqualification and team fine	-	\$ 3,000	132
Jay Howard Driver Development	6	F4	Mid-Ohio Sports Car Course	28 June 2020	Race 2	26.1/Technical Regulations 2.7.1 - Modified engine oil pressure sensor	Disqualification and team fine	-	\$ 3,000	131
Jay Howard Driver Development	5	F4	Mid-Ohio Sports Car Course	28 June 2020	Race 2	26.1/Technical Regulations 2.7.1 - Modified engine oil pressure sensor	Disqualification and team fine	-	\$ 3,000	130
Jay Howard Driver Development	4	F4	Mid-Ohio Sports Car Course	28 June 2020	Race 2	26.1/Technical Regulations 2.7.1 - Modified engine oil pressure sensor	Disqualification and team fine	-	\$ 3,000	129
Jay Howard Driver Development	3	F4	Mid-Ohio Sports Car Course	28 June 2020	Race 2	26.1/Technical Regulations 2.7.1 - Modified engine oil pressure sensor	Disqualification and team fine	-	\$ 3,000	128
Jay Howard Driver Development	7	F4	Mid-Ohio Sports Car Course	27 June 2020	Race 1	26.1/Technical Regulations 2.7.1 - Restricted or undersized engine oil suction screen assembly	Disqualification, team fine and start from pit lane at next 3 races	-	\$ 3,000	115 (a)
Jay Howard Driver Development	6	F4	Mid-Ohio Sports Car Course	27 June 2020	Race 1	26.1/Technical Regulations 2.7.1 - Restricted or undersized engine oil suction screen assembly	Disqualification, team fine and start from pit lane at next 3 races	-	\$ 3,000	114 (a)
Jay Howard Driver Development	7	F4	Mid-Ohio Sports Car Course	27 June 2020	Race 1	Technical Regulations 2.7.1 - Shock cover fasteners added	Team reprimand	1	\$ -	113
Jay Howard Driver Development	4	F4	Mid-Ohio Sports Car Course	27 June 2020	Race 1	Technical Regulations 2.7.1 - Shock cover fasteners added	Team reprimand	1	\$ -	112
Jay Howard Driver Development	8	F4	Mid-Ohio Sports Car Course	27 June 2020	Race 1	39.5(b) - Car worked on during a race suspension	Team reprimand	1	\$ -	109
Jay Howard Driver Development	7	F4	Mid-Ohio Sports Car Course	27 June 2020	Race 1	39.5(b) - Car worked on during a race suspension	Team reprimand	1	\$ -	108
Jay Howard Driver Development	11	FR	Mid-Ohio Sports Car Course	25 June 2020	Pre-Event Tech	26.1/Tech Regs 15.2.5/Ligier JS F3 Tech Memo #1 - Halo FIA label and hologram	Team reprimand and sealing and confiscation of component	1	\$ -	101
Jay Howard Driver Development							Total Reprimands and Fines	6	\$ 31,100	

(a) The Competitor lodged Appeals against decisions 114 and 115. On 17 July 2020, SCCA's National Court of Appeal rejected each Appeal and confirmed the decisions of the Stewards.

Velocity Racing Development	11	F4	Barber Motorsports Park	01 August 2020	Race 1	26.3(b) - Fire extinguisher not in armed position for on track session	Team reprimand	1	\$ -	308
Velocity Racing Development	11	F4	Virginia International Raceway	18 July 2020	Race 1	26.3(b) - Fire extinguisher not in armed position for on track session	Team reprimand	1	\$ -	212
Velocity Racing Development							Total Reprimands and Fines	2	\$ -	