



LIGIER JS F3

Ligier JS F3 | Tech Memo

#5 – 3.23.2021



08-02-9009 FRONT TRACK ROD

A defect has been identified in the front track rod manufacturing. Please bring current front track rods to the Ligier Automotive trailer at Road Atlanta or the next event for a replacement. If a team is not attending races please contact usparts@ligierautomotive.com.

