



FR Technical Advisory Memo

No: TAMFR-2021-018
Date: September 16, 2021
Subject: Cooling System Air Bleed Procedure

HPD has updated the recommended procedure for thorough bleeding of the FR engine cooling system to reduce potential confusion with previous recommendations and improve the consistency of cooling system performance.