

F4 ECU Update Technical Bulletin # F4-2020-EN002-00

Approval



This Technical Bulletin provides information on an ECU update to be performed to add rear light functionality in an engine stall situation. This update **MUST** be performed in conjunction with the rear light upgrades from Ligier for proper light function.

Overview

Engine service provider Mountune USA will perform the updates on the ECUs. Each ECU must be shipped to Mountune USA for update.

In preparation for shipping, please ensure that each ECU is marked clearly with the team name and is sufficiently protected from shipping damage. Each team must also include a return shipping label to ensure timely return.

ECU update cost to the team is **\$100 each**. Please contact HPD at grmsadmin@hra.com to arrange payment for the update prior to or just after shipping to Mountune. The update fee must be paid before the ECU can be returned to the team.

Due to limited at-track resource, there will be a significant upcharge for any updates that have to be performed at the first event.

ECUs may be sent to Mountune any time between May 11, 2020 and June 8, 2020.

A new team GIN file (GDI80-02H38 Team V013.GIN) will be posted on the Ligier FTP site.

Shipping Address:

Mountune USA
1000 E Carson St
Carson, CA 90745

If you have any questions regarding the content of this bulletin, please contact Andrew Salzano at asalzano@hra.com or GRMS Admin at GRMSAdmin@hra.com.

This document is confidential and is supplied on express condition that it shall not be lent, copied, or disclosed to any other person, or used for any other purpose without the written consent of Honda Performance Development.