

F4 Technical Advisory Memo

No: TAMF4-2020-014

Date: June 2, 2020

Subject: HPD Bulletin F4-2020-EL001-00 Wiring Harness Service

See the attached bulletin for engine harness service offered through BMRS. Also attached is the new customer form to send with harnesses.

