

## FR Technical Advisory Memo

**No:** TAMFR-2020-013

**Date:** June 2, 2020

**Subject:** HPD Bulletin FRA-2020-EL001-00 Wiring Harness Service

See the attached bulletin for engine harness service offered through BMRS. Also attached is the new customer form to send with harnesses.